


# Toleranstabell för skjutmått enligt DIN 862.



Referenstemp. + 20°C.

Längdmått . . . . .	mm	0-200	200-300	300-400	400-500	500-600
Max. avvikelse . . . . .	mm	±0.04	±0.05	±0.07	±0.08	±0.09
Längdmått . . . . .	mm	600-700	700-800	800-900	900-1000	1000-1100
Max. avvikelse . . . . .	mm	±0.10	±0.11	±0.12	±0.13	±0.14
Längdmått . . . . .	mm	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600
Max. avvikelse . . . . .	mm	±0.16	±0.17	±0.18	±0.19	±0.20
Längdmått . . . . .	mm	1600-1700	1700-1800	1800-1900	1900-2000	2000-
Max. avvikelse . . . . .	mm	±0.21	±0.22	±0.23	±0.24	±0.25